## Oil Field Environmental Incident Summary

**Responsible Party:** CONTINENTAL RESOURCES, INC. **Well Operator:** CONTINENTAL RESOURCES, INC.

Well Name: HOGAN 1-16H

Field Name: HAYSTACK BUTTE Well File #: 19627

Date Incident:9/18/2015Time Incident:15:30Facility ID Number:County:MCKENZIETwp:148Rng:98Sec:16Qtr:

**Location Description:** 

Submitted By: Todd Senescall Received By:

Contact Person: Shane Teigen

PO BOX 268870

OKLAHOMA CITY, OK 73126

General Land Use: Pasture Affected Medium: Topsoil

**Distance Nearest Occupied Building:** 

Distance Nearest Water Well:

Type of Incident: Fire

Release Contained in Dike: Yes - On Constructed Well Site Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil 2 Gallons 2 Gallons

**Brine** 

Other

**Description of Other Released Contaminant:** 

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

fire

Areal Extent:

Approximately 2 acres of pasture was burned.

## Potential Environmental Impacts:

none

## Action Taken or Planned:

Rural fire department extinguisher the fire. Ensure that flare lines on purged of fluid before opening the flare regulator.

Wastes Disposal Location: N/A

Agencies Involved: Local Fire Department, Joyce Kohut-NDIC Inspector, Cory Barth-ND Trust

Lands, Brian Zingleman - tenant

## **Updates**

Date: 9/21/2015 Status: Reviewed - No Action Required Author: Souder, Taylor

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

Notes:

Due to small volue and fire, no follow-up is required

Date: 3/10/2016 Status: Correspondence Author: Suess, Bill

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

Notes:

Bill Suess sent a No Further Action letter dated March 10, 2016.